Batch Print

Batch print drawings with the same drawing frame attribute.

Menu : Express tools>Plot Tool>Batch Print

Command Entry : BP

Operation steps:

1. Start the command.

2. Specify the type of frame, you can select Layer/ Block/ Polyline so that the system can recognize the frame.

3. Corner select the frame you want to print, you will get a dialog box as below.

Batch Plot Setup

Specify batch setup

Filter Base:layer   0   [Select from drawing]

Current window:(21.94,259.12),(267.23,62.53)   [Re-specify selected box]

According to the selected info, need to plot 2 frames   [Draw frame boxes]

Plot Setup _Options

Plotter Name: Canon MF4400 Series UFRII LT

Page Name: Model   Paper Size: A4

With Plot styles: Yes   Style Table: None

Plot Linewidths: Yes   Drawing Orientation: Portrait&Not upside-down

Orientation

⦿ Center   ○ Offset   X= 0.000000   Y= 0.000000

Plot

Plot Objects: Plot to file

Prefix Name: PLOT_   Extended Name: .PLT   ☑ Delete existed duplicate file

Saved Location: E:\Program Files\GstarCAD2013 Profess   [Browse...]

Plot Scale

○ Fit Paper   ⦿ Fixed Scale   Scale 1.000000 : 1.000000

Units: Millimeter

[OK]   [Apply to Layout]   [Cancel]

4. Set the print Parameters, click "OK" to execute bath print.