Super Axonometric

1060 kbadmin June 30, 2021 Unique function 0 4889

It is a quintessential function that can easily convert a plan drawing to an axonometric drawing.

> Menu : Express > GstarCAD Tools > Super Axonometric
> Command Entry : ZC

Operation steps:

1.Start the command.

2.Select objects and press enter, as shown below.



3.Enter the axonometric point of view, such as 45 degree.

4.The effect will be as below.



Online URL: https://www.kb2.gstarcad.com.my/article.php?id=1060