3DXORBIT command

The **3DXORBIT** command is used to orbit along the Z axis.

Command Access:

Ribbon : View >Navigate 2D>Orbit along the Z-axis

Online URL: https://www.kb2.gstarcad.com.my/article.php?id=1946