DELEDATA command

The **DELEDATA** command used to delete the application-specific data attached to the object.

Command Access:

Command entry : DELEDATA

Command Prompts:

Delete object data: ?list application/<name >:

Input the application name of the deleted object data. Press "?" the application name of the current drawing can be listed.

Select the deleted data object:

The application will delete the selected data objects. Every object contains common data set, such as: layer, linetype, color and linetype scale and also has it's own special data, such as the start point of line, endpoint or diameter of circle. Except these two kind of data, you can create new application to your object. You can add data to one object from multiple applications or move/copy data to other object. You can also delete some special data of some objects.

Online URL: https://www.kb2.gstarcad.com.my/article.php?id=2071