DIMCENTER command

The **DIMCENTER** command is used to create center marks or center lines for circles or arcs.

Command Access:

Ribbon : Annotation > Dimension > DIMCENTER
Menu : Dimension > Center Mark
Command : DIMCENTER

Command Prompts:

Select arc or circle:

Function Description:

The circle center could display as center mark or center lines. Users could set options of Center marks in Dimension Style Manager in Symbols and Arrows tab.

Uses could change display of center mark or modify its size in Dimension Style Manager. They could also change its settings by DIMCEN system variable.

center mark   center lines

Related tutorial video:

Above video sources from TUTORIAL - GETTING STARTED WITH GSTARCAD, enrol now for free.