LIGHTLIST command

The **LIGHTLIST** command is used to turn on or turn off the "Lights in Model" palette.

Command Access:

Menu : View > Render > Light> Light List
Command : LIGHTLIST

Function Description:

The "Lights in Model" palette is used to list all lights in model. Select one or more lights and Right-click, the shortcut menu displays. Users could delete or change properties of selected light.

Lights in Model

Lights in model:

Type	Light Name	
💡	Point4	

Click a light on the list to select it in the model. Use CTRL for multiple selection. Note: Distant lights and the sun do not appear as interface objects in the model.

Online URL: https://www.kb2.gstarcad.com.my/article.php?id=2199