RECTANG command

The **RECTANG** command is used to create rectangles.

Command Access:

Ribbon : Home > Draw > Polyline > Rectangle
Menu : Draw > Rectangle
Command : RECTANG

Command Prompts:

Specify first corner point or [Chamfer/Elevation/Fillet/Thickness/Width]:
Specify other corner point or [Area/Dimensions/Rotation]:

Function Description:

Users could use this command to specify the rectangle parameters (length, width, and rotated angle) and control corner types (Fillet, chamfer or right angle).

**Relative Glossary:**

First corner point:
Specify the first corner point of a rectangle.

Other corner point:
Specify another corner point to create a rectangle.

Area : Create a rectangle by area and length or width. It could create chamfers or fillets on the rectangle by setting the "chamfer" or "fillet" option.

Dimensions : Create a rectangle by length and width.
**Rotation :** Create a rectangle by rotation angle.

Chamfer : Specify chamfer distance for a rectangle.
Elevation : Specify elevation of a rectangle.
Fillet : Specify fillet radius for a rectangle.
Thickness : Specify thickness of a rectangle.
Width : Specify line width for a rectangle.

Related tutorial video:

Above video sources from TUTORIAL - GETTING STARTED WITH GSTARCAD, enrol now for free.

- [Union command](#) 01:50
- [Xedges command](#) 02:03
- [Filletedge command](#) 02:08
- [Vscurrent command](#) 02:45
- [Extrude command](#) 03:27
- [Rectang command](#) 04:22
- [Move command](#) 04:45
- [Line command](#) 05:06
- [ARC command](#) 05:16
- [Trim command](#) 05:23
- [Join command](#) 05:46
- [Convtosurface command](#) 06:35
- [Slice command](#) 06:51
- [Solidedit](#) 08:32

Above video sources from [TUTORIAL - GETTING STARTED WITH GSTARCAD](#), enrol now for free.