

LAYERPMODE Command — GstarCAD 2026

6881 kbadmin September 26, 2026 [Command Reference 2026](#) 0 7

LAYERPMODE Command

[GstarCAD 2026](#) · [Command Reference](#)

Commands > L Command > LAYERPMODE

Function Description:

This command is used to turn on or turn off the trace mode about layer settings.

Command Access:

Icon: /
Menu: /
Ribbon: /
Toolbar: /
Command: LAYERPMODE
Alias: /

Command Prompts:

Enter LAYERP mode [ON/OFF] <On>:

ON

If the LAYERP mode is turned on, layer changes will be traced.

OFF

If the LAYERP mode is turned off, layer changes will not be traced.

Related References?

- [Commands about Layers](#)

Related Tasks?

- [To Work with Layers](#)
- [To Lock or Unlock a Layer](#)
- [To Change the Visibility of Layers](#)

Other versions with matching text

[2023](#) · [2024](#) · [2025](#) · [2027](#)

Online URL: <https://www.kb2.gstarcad.com.my/article.php?id=6881>