


# How to convert a dwg file to pdf with added layer information?


1139 kbadmin April 14, 2016 [Tips & Tricks](#) 0 11104

At plot model dialog box choose **DWG to PDF.pc3** as the printer/plotter name.



Configure your desired options, such as Paper size, Plot area, and Plot scale.

Click **Properties > Custom Properties**, in the **Additional Output Settings** category choose **Include layer information**.



Online URL: <https://www.kb2.gstarcad.com.my/article.php?id=1139>