

DRAWINGRECOVERYHIDE command

2100 GstarCAD MY /KW August 12, 2021 [CAD Commands](#) 0 2405

The **DRAWINGRECOVERYHIDE** command is used to close Drawing Recovery Manager.

Command Access:

Command : DRAWINGRECOVERYHIDE

Online URL: <https://www.kb2.gstarcad.com.my/article.php?id=2100>