## **Erase Objects**


## 2545 GstarCAD MY /KW November 9, 2021 Workflow 0 2333

If you want to erase objects from your drawing, you can do one of the following.

Use the command **ERASE**.

Select objects and press DELETE.

Select objects and then cut them to the Clipboard with CTRL+X



Objects, which were recently erased with  $\underline{ERASE}$ ,  $\underline{BLOCK}$  or  $\underline{WBLOCK}$  can all be restored with the  $\underline{OOPS}$  command.

Blips, which are plus-shaped markers and left over stray pixels that are displayed, can be removed by REDRAW ( $\underline{REDRAWALL}$ ) or  $\underline{REGEN}$ .

Unused named Objects like block definitions, dimension styles (<u>DIMSTYLE</u>), layers (<u>LAYER</u>), <u>LINETYPE</u> and <u>TEXTSTYLE</u> can be removed with the <u>PURGE</u> command.

Online URL: <a href="https://www.kb2.gstarcad.com.my/article.php?id=2545">https://www.kb2.gstarcad.com.my/article.php?id=2545</a>