

WIPEOUT Command — GstarCAD 2027

2881 kbadmin September 25, 2026 [Command Reference](#) 0 17

WIPEOUT Command

[GstarCAD 2027](#) · [Command Reference](#)

Commands > W Command > WIPEOUT

Function Description:

This command is used to create a region to cover objects and control whether to display the frame of region in the drawing.

GstarCAD brings you the WIPEOUT command enhanced with more options. Now this command can use a circle object to be wipeout or even you can pick up a closed polyline object containing arcs.

Users can use this command to create a polygonal region to cover objects. The color of the polygonal region is the same as the current background. Users can select the polyline boundary for editing, they can also turn off its line frame for plotting.

Command Access:

Menu: Draw > Wipeout

Ribbon: Home > Draw > Wipeout

Toolbar: /

Command: WIPEOUT

Alias:

/

Command Prompts:

Specify first point or [Frames/Circle/Pick polyline or circle/Accuracy] <Pick polyline or circle >:

First point

Specifies the first point of the polyline.

Frames

Determines whether to display the frame of the region.

Circle

Selects a circle as the region boundary to cover objects.

Pick polyline or circle

Selects a polyline or a circle as the region boundary to cover objects.

Accuracy

Specifies the accuracy of a circle and an arc segment of the pline.

Related Tasks?

- [To Toggle Wipeout Frames](#)
- [To Mask a Drawing Area](#)

Other versions with matching text

[2023](#) · [2024](#) · [2025](#) · [2026](#)

Online URL: <https://www.kb2.gstarcad.com.my/article.php?id=2881>

