

CVADD Command — GstarCAD 2027

4230 kbadmin September 25, 2026 [Command Reference](#) 0 18

CVADD Command

[GstarCAD 2027](#) · [Command Reference](#)

Commands > C Command > CVADD

Function Description:

This command is used to add control vertices to NURBS surfaces and splines.

Command Access:

Menu: Modify > Surface Editing > NURBS Editing > Add CV

Ribbon: Surface > CV > Add

Toolbar: /

Command: CVADD

Alias: /

Command Prompts:

Select a NURBS surface or curve
to add control vertices:

Related References?

- [Commands about
Constructing 3D Solids and Surfaces from 2D Geometry](#)

Other versions with matching text

[2023](#) · [2024](#) · [2025](#) · [2026](#)

Online URL: <https://www.kb2.gstarcad.com.my/article.php?id=4230>