

Overview of Layers — GstarCAD 2027

5784 kbadmin September 26, 2026 [Command Reference](#) 0 17

Overview of Layers

[GstarCAD 2027](#) · [Command Reference](#)

As the main organizational tool for drawings, layers can be used to group information by function and to enforce linetype, color and other standards.

The following settings can be controlled: the default color, default linetype and lineweight, visibility and brightness, modify and display objects with different layer properties in individual layout viewports.

You start each new drawing with a layer named 0. This layer 0 cannot be deleted or renamed for the following reasons:

- Every drawing has at least one layer
- It is a special layer that relates to controlling colors in blocks

Other versions with matching text

[2023](#) · [2024](#) · [2025](#) · [2026](#)

Online URL: <https://www.kb2.gstarcad.com.my/article.php?id=5784>