

To Create a 3D Solid Shell — GstarCAD 2027

6159 kbadmin September 26, 2026 [Command Reference](#) 0 12

To Create a 3D Solid Shell

[GstarCAD 2027](#) · [Command Reference](#)

To Create a 3D Solid Shell

1. Click Modify > Solid Editing > Shell on the main menu.
2. Select the 3D solid.
3. Select one or more faces to be excluded from shelling and press Enter.
4. Enter the shell offset distance.
5. Press Enter to complete the command.

Other versions with matching text

[2023](#) · [2024](#) · [2025](#) · [2026](#)

Online URL: <https://www.kb2.gstarcad.com.my/article.php?id=6159>