

To Create a Dimension Break Manually — GstarCAD 2027

6162 kbadmin September 26, 2026 [Command Reference](#) 0 10

To Create a Dimension Break Manually

[GstarCAD 2027](#) · [Command Reference](#)

To Create a Dimension Break Manually

1. Click Dimension > Dimension Break on the main menu.
2. Select a dimension to add/remove break.
3. Enter M at the command prompt.
4. Specify the first break point.
5. Specify the second break point.

Other versions with matching text

[2023](#) · [2024](#) · [2025](#) · [2026](#)

Online URL: <https://www.kb2.gstarcad.com.my/article.php?id=6162>