

To Create an Inspection Dimension — GstarCAD 2027

6186 kbadmin September 26, 2026 [Command Reference](#) 0 17

To Create an Inspection Dimension

[GstarCAD 2027](#) · [Command Reference](#)

To Create an Inspection Dimension

1. Click Dimension > Inspection on the main menu.
2. The Inspection Dimension dialog box is displayed, click Select dimensions. The Inspection Dimension dialog box closes. You are prompted to select dimensions.
3. Select the dimension you want to make an inspection dimension. Press Enter to return to the dialog box.
4. Under the Shape section, specify the frame type.
5. Under the Label/Inspection rate section, specify the desired options.
6. Click OK.

Other versions with matching text

[2023](#) · [2024](#) · [2025](#) · [2026](#)

Online URL: <https://www.kb2.gstarcad.com.my/article.php?id=6186>