

To Display Only Selected Objects — GstarCAD 2027

6195 kbadmin September 26, 2026 [Command Reference](#) 0 9

To Display Only Selected Objects

[GstarCAD 2027](#) · [Command Reference](#)

To Display Only Selected Objects

1. Select objects that you want to keep visible. All other objects will be temporarily invisible.
2. Right-click the selected objects and choose Isolation > Isolate Objects. To restore all hidden objects, right-click in the drawing area and choose Isolation > End Object Isolation.

Other versions with matching text

[2023](#) · [2024](#) · [2025](#) · [2026](#)

Online URL: <https://www.kb2.gstarcad.com.my/article.php?id=6195>