

To Display a List of the Underlays Attached to a Drawing — GstarCAD 2027

6198 kbadmin September 26, 2026 [Command Reference](#) 0 9

To Display a List of the Underlays Attached to a Drawing

[GstarCAD 2027](#) · [Command Reference](#)

To Display a List of the Underlays Attached to a Drawing

1. Click Insert > External References on the main menu.
2. The External Reference palette is displayed, click the List View button.

Other versions with matching text

[2023](#) · [2024](#) · [2025](#) · [2026](#)

Online URL: <https://www.kb2.gstarcad.com.my/article.php?id=6198>