

To Display or Hide Lineweights — GstarCAD 2027

6201 kbadmin September 26, 2026 [Command Reference](#) 0 10

To Display or Hide Lineweights

[GstarCAD 2027](#) · [Command Reference](#)

To Display or Hide Lineweights

You can use one of the following methods:

- Click the Line Weight button on the status bar.
- Click Format > Lineweight on the main menu, the Lineweight Settings dialog box is displayed, in which you can select Display Lineweight button.

Other versions with matching text

[2023](#) · [2024](#) · [2025](#) · [2026](#)

Online URL: <https://www.kb2.gstarcad.com.my/article.php?id=6201>