

To Set Options for Plotted Objects — GstarCAD 2027

6315 kbadmin September 26, 2026 [Command Reference](#) 0 7

To Set Options for Plotted Objects

[GstarCAD 2027](#) · [Command Reference](#)

To Hide Paper Space Objects

1. Click File > Plot on the main menu.
2. The Plot dialog box is displayed, under Plot Options, select Hide Paperspace Objects.
3. Click OK.

To Plot Lineweights

1. Click File > Plot on the main menu.
2. The Plot dialog box is displayed, under Plot Options, select Plot Object Lineweights.
3. Click OK.

To Plot Transparency

1. Click File > Plot on the main menu.
2. The Plot dialog box is displayed, under Plot Options, select Plot with Transparency.
3. Click OK.

To Turn off Plot Styles

1. Click File > Plot on the main menu.
2. The Plot dialog box is displayed, under Plot Options, clear the Plot with Plot Styles option.
3. Click OK.

Other versions with matching text

[2023](#) · [2024](#) · [2025](#) · [2026](#)

Online URL: <https://www.kb2.gstarcad.com.my/article.php?id=6315>