

# To Specify a New UCS Orientation With Three Points — GstarCAD 2027

6327 kbadmin September 26, 2026 [Command Reference](#) 0 18

## To Specify a New UCS Orientation With Three Points

[GstarCAD 2027](#) · [Command Reference](#)

### To Specify a New UCS Orientation With Three Points

1. Click Tools > New UCS > 3 Point on the main menu.
2. Specify the new origin point.
3. Specify the point on positive portion of X-axis.
4. Specify the point on positive-Y portion of the UCS XY plane.

### Other versions with matching text

[2023](#) · [2024](#) · [2025](#) · [2026](#)

Online URL: <https://www.kb2.gstarcad.com.my/article.php?id=6327>