

To Work with Jogged Linear Dimensions — GstarCAD 2027

6364 kbadmin September 26, 2026 [Command Reference](#) 0 20

To Work with Jogged Linear Dimensions

[GstarCAD 2027](#) · [Command Reference](#)

To Create Jogged Linear Dimensions

1. Click Dimension > Jogged Linear on the main menu.
2. Select the dimension to add jog.
3. Specify the jog location.

To Relocate a Jog on a Linear Dimension Using Grips

1. Select a linear dimension that has the jog you want to reposition.
2. Select the grip in the middle of the jog.
3. Drag the crosshairs along the dimension line and click to reposition the jog.

To Remove a Jog on a Linear Dimension

1. Click Dimension > Jogged Linear on the main menu.
2. Enter R at the command prompt.
3. Select the jog to remove.

Other versions with matching text

[2023](#) · [2024](#) · [2025](#) · [2026](#)

Online URL: <https://www.kb2.gstarcad.com.my/article.php?id=6364>