


Copy Command


1027 kbadmin April 14, 2022 [CAD Commands](#) 0 7862

(Enhancement) There are three options: measure(E), divide(I), path(P) options are added in copy command, user can easily finish the drawing without the assistance of other operations such as divided by segment, by distance, array, or layout bypath in previous version.


1. measure(E) when users need to copy objects with same distance and same direction, this option will be very useful.



2. Divide(I), you can copy many objects with same distance in a specified distance.



3. Path(P) After select the path option, you can select divide or measure option again to locate the count objects.



Related tutorial video:

- [Status bar related setting](#) 00:15
- [Draw Rectangles and Polygons](#) 00:26
- [Rectang command](#) 00:26
- [Polygon command](#) 00:26
- [Arc command](#) 00:30
- [Trim command](#) 00:40
- [Extend command](#) 01:51
- [Offset command](#) 02:23
- [Stretch command](#) 03:35
- [Edit objects + grips](#) 03:55

- [Break object](#) 04:13
- [Circle command](#) 05:51
- [Draw circles](#) 05:51
- [Break command](#) 05:56
- [Join command](#) 06:32
- [Scale command](#) 06:53
- [Lengthen command](#) 07:29
- [Copy command](#) 08:20
- [Rotate command](#) 08:47
- [Move command](#) 09:07

Above video sources from [TUTORIAL - GETTING STARTED WITH GSTARCAD](#), enrol now for free.

Online URL: <https://www.kb2.gstarcad.com.my/article.php?id=1027>