

3DYORBIT command

1947 GstarCAD MY /KW July 30, 2021 [CAD Commands](#) 0 2520

The **3DYORBIT** command is used to orbit along the Y axis

Command Access:

Ribbon : View >Navigate 2D>Orbit along the Y-axis

Online URL: <https://www.kb2.gstarcad.com.my/article.php?id=1947>