

# LIGHTLIST command

2199 GstarCAD MY /KW August 17, 2021 [CAD Commands](#) 0 2532

The **LIGHTLIST** command is used to turn on or turn off the "Lights in Model" palette.

## **Command Access:**

**Menu** : View > Render > Light> Light List


**Command** : LIGHTLIST

## **Function Description:**

The "Lights in Model" palette is used to list all lights in model. Select one or more lights and Right-click, the shortcut menu displays. Users could delete or change properties of selected light.

Lights in Model

Lights in model:

| Type  | Light Name |
|---|------------|
|  | Point4     |

Click a light on the list to select it in the model. Use CTRL for multiple selection.  
Note: Distant lights and the sun do not appear as interface objects in the model.

Online URL: <https://www.kb2.gstarcad.com.my/article.php?id=2199>