

OOPS command

2260 GstarCAD MY /KW August 19, 2021 [CAD Commands](#) 0 2175

The **OOPS** command is used to restore the last deleted objects.

Command Access:

Command : OOPS

Function Description:

This command could restore the last deleted objects by ERASE command. The OOPS command could not restore parameters, actions or pinch points in "Block Editor", as well objects deleted by PURGE command.

Online URL: <https://www.kb2.gstarcad.com.my/article.php?id=2260>