

3DORBIT — GstarCAD 2027

2803 kbadmin September 25, 2026 [User Guide](#) 0 18

3DORBIT

[GstarCAD 2027](#) · [User Guide](#)

User Guide > Control the Views > Specify 3D Views > 3D Orbit

By using the mouse or another pointing devices, you can move a drawing to view the drawing object from different angles.

When you activate 3D navigation, you can pan and zoom at the same time. During a 3D navigation operation, it is not allowed to manage or edit entities in the drawing.

Press ENTER, ESC or click the right-mouse button to display the shortcut menu, you can close 3D navigation by selecting "Exit" in the shortcut menu.

Note: Raster images and OLE objects can not be displayed in the 3D navigation view.

Other versions with matching text

[2022](#) · [2023](#) · [2024](#) · [2025](#) · [2026](#)

Online URL: <https://www.kb2.gstarcad.com.my/article.php?id=2803>