

FSMODE Command — GstarCAD 2027

3072 kbadmin September 25, 2026 [Command Reference](#) 0 9

FSMODE Command

[GstarCAD 2027](#) · [Command Reference](#)

Commands > F Command > FSMODE

Function Description:

This command is used to control the behavior of the FASTSEL/FS command.
If FSMODE is set to ON, FS
selects all the objects that are touching the selected object as well as any
objects that are touching those objects. The selection process continues
down the chain of unselected objects that are touching the selected object
until no more unselected objects are visible in the drawing area.

Command Access:

Icon: /
Menu: /
Ribbon: /
Toolbar: /
Command: FSMODE
Alias: /

Command Prompts:

FASTSEL chain selection <OFF/ON>:

Other versions with matching text

[2022](#) · [2023](#) · [2024](#) · [2025](#) · [2026](#)

Online URL: <https://www.kb2.gstarcad.com.my/article.php?id=3072>