

MLEADEREDIT Command — GstarCAD 2027

3635 kbadmin September 25, 2026 [Command Reference](#) 0 8

MLEADEREDIT Command

[GstarCAD 2027](#) · [Command Reference](#)

Commands > M Command > MLEADEREDIT

Function Description:

This command is used to add a leader to a multileader object or remove a leader from a multileader object.

Command Access:

Menu: Modify > Object > Multileader > Add Leader/Remove Leader

Ribbon: Annotation > Leader > MLEADEREDIT

Toolbar: Multileader > Add Leader/Remove Leader

Command: MLEADEREDIT

Alias: MLE

Command Prompts:

Select Multileader:

Specify leader arrowhead
location or [Remove leaders]:

Add leader

Adds a leader line to a selected multileader object. The new leader line is added to the right or left of the selected multileader according to the location of the cursor.

Remove leader

Removes a leader line from a selected multileader object.

Related References?

- [Commands about Creating Leaders](#)

Related Tasks?

- [To Create a Leader With Lines](#)
- [To Create a Spline Leader With Text or a Block](#)
- [To Create Multiple Leaders From the Same Annotation](#)

Other versions with matching text

[2023](#) · [2024](#) · [2025](#) · [2026](#)

Online URL: <https://www.kb2.gstarcad.com.my/article.php?id=3635>