

DIMINSPECT Command — GstarCAD 2027

4361 kbadmin September 25, 2026 [Command Reference](#) 0 10

DIMINSPECT Command

[GstarCAD 2027](#) · [Command Reference](#)

Commands > D Command > DIMINSPECT

Function Description:

This command is used to add or remove inspection information for a selected dimension. The inspection dimensions specify how frequently manufactured parts should be checked, in order to keep the dimension value and tolerances of the parts are within the specified range. The [Inspection Dimension dialog box](#) is displayed.

Command Access:

Menu: Dimension > Inspection

Ribbon: Annotation > Dimension > DIMINSPECT

Toolbar: Dimension > DIMINSPECT

Command: DIMINSPECT

Alias: /

Command Prompts: /

Related References?

- [Commands about Inspection Dimensions](#)

Related Tasks?

- [To Create an Inspection Dimension](#)

Other versions with matching text

[2023](#) · [2024](#) · [2025](#) · [2026](#)

Online URL: <https://www.kb2.gstarcad.com.my/article.php?id=4361>