

CBK — GstarCAD 2027

5087 kbadmin September 25, 2026 [Command Reference](#) 0 8

CBK

[GstarCAD 2027](#) · [Command Reference](#)

In engineering drawings, many places need to break the cross line. If we do this the original way, it will be very complex. Using this function breaking lines can be easily done.

Operation Steps:

- 1.Start the command.
- 2.Specify the occluded line.
- 3.Choose the occluded (to be disconnected) line and what you selected will be cut off automatically.
- 4.Enter to finish the command, the effect will be as below.

Other versions with matching text

[2025](#) · [2026](#)

Online URL: <https://www.kb2.gstarcad.com.my/article.php?id=5087>