

To Create a Planar Surface — GstarCAD 2027

6170 kbadmin September 26, 2026 [Command Reference](#) 0 12

To Create a Planar Surface

[GstarCAD 2027](#) · [Command Reference](#)

To Create a Planar Surface

1. Click Surface tab > Create panel > Plan in the ribbon.
2. Specify the first corner of the surface.
3. Specify the other corner of the surface.

Other versions with matching text

[2023](#) · [2024](#) · [2025](#) · [2026](#)

Online URL: <https://www.kb2.gstarcad.com.my/article.php?id=6170>