

To Rename or Delete a Visibility State — GstarCAD 2027

6297 kbadmin September 26, 2026 [Command Reference](#) 0 11

To Rename or Delete a Visibility State

[GstarCAD 2027](#) · [Command Reference](#)

To Rename or Delete a Visibility State

1. Click Insert tab > Block Definition panel > Block Editor in the ribbon.
2. The Edit Block Definition dialog box is displayed, select the block you want to modify.
3. Click the Block Editor ribbon contextual tab > Visibility panel > Visibility States.
4. The Visibility States dialog box is displayed, select a visibility state from the list.
5. Click Rename and enter a new name for the visibility state or click Delete.

Other versions with matching text

[2023](#) · [2024](#) · [2025](#) · [2026](#)

Online URL: <https://www.kb2.gstarcad.com.my/article.php?id=6297>