

To Show and Hide Raster Images Frames — GstarCAD 2027

6323 kbadmin September 26, 2026 [Command Reference](#) 0 18

To Show and Hide Raster Images Frames

[GstarCAD 2027](#) · [Command Reference](#)

To Show and Hide Raster Images Frames

1. Enter the IMAGEFRAME at the command prompt.
2. Enter a new value for the IMAGEFRAME system variable.

Other versions with matching text

[2023](#) · [2024](#) · [2025](#) · [2026](#)

Online URL: <https://www.kb2.gstarcad.com.my/article.php?id=6323>